CAPITAL IMPROVEMENT RECOMMENDATIONS
CIPP LINING (MAJOR SEVERITY)
CIPP LINING (MODERATE SEVERITY)

0 2000 4000
1"=2000

S. DAHLIA ST.
S. DEXTER ST.
S. EUDORA ST.
S. ELM CT.
S. HOLLY ST.
S. IVANHOE LN.
S. IVY LN.
S. HAPPY CANYON RD.
HAPPY CANYON DR.
HOLLY WAY
W. NASSAU CIR.
E. NASSAU CIR.
E. NASSAU PL.
W. SANFORD CIR.
E. SANFORD CIR.
S. HUDSON WAY
S. HUDSON PKWY.
E. OXFORD AVE.
E. OXFORD PL.
E. PRINCETON AVE.
E. QUINCY AVE.
S. FOREST CIR.
S. FOREST CT.
CHERRY HILLS EAST
HONEY-LOCUST DR.
SOUTHMOOR VISTA
SOUTHMOOR LN.
SOUTHMOOR CIR.
PRINCETON EAST
PRINCETON CIR.

HC8.117 HC8.115 HC8.111A HC8.110 HC8.109 HC8.108 HC8.62 HC8.61 HC8.60 HC8.59 HC8.58 HC8.58A HC8.30 HC8.57 HC8.38 HC8.39 HC8.37 HC8.36 HC8.40 HC8.43 HC8.41 HC8.44 HC8.45 HC8.42 HC8.47 HC8.46 HC8.35 HC8.34 HC8.33 HC8.44.1 HC8.32 HC8.31 HC8.23 HC8.22 HC8.24 HC8.25 HC8.27 HC8.28 HC8.29 HC8.26 HC8.104 HC8.101 HC8.100 HC8.99 HC8.98 HC8.97 HC8.96 HC8.95 HC8.94 HC8.93 HC8.92 HC8.90 HC8.89 HC8.89.1 HC8.88 HC8.87 HC8.86 HC8.85 HC8.84 HC8.83 HC8.83A HC8.82 HC8.81 HC8.80 HC8.111 HC8.113 HC8.114 HC8.112 HC8.107 HC8.106 HC8.74 HC8.73 HC8.72 HC8.67 HC8.66.1 HC8.66 HC8.65 HC8.105 HC8.79 HC8.78 HC8.77 HC8.76 HC8.75 HC8.71 HC8.70 HC8.69 HC8.68 HC8.64 HC8.63 HC8.21 HC8.20 HC8.19 HC8.18 HC8.17 HC8.50 HC8.56C HC8.48 HC8.52 HC8.51 HC8.49 HC8.56 HC8.54 HC8.53 HC8.55 HC8.56B HC8.56A HC8.16 HC8.14 HC8.15 HC8.10 HC8.09 HC8.08 HC8.07 HC8.06 HC8.05 HC8.04 HC8.03 HC8.02 HC8.01 HC8.13 HC8.12 HC8.11A

STUBOUT 93.6'~8"

P:\CAD\2009\0946037_HCWS_Basin_2_Video_Review_20090946037_CIP.dwg 5/6/2009 11:17 AM SARAH LEVY

USE OF DOCUMENTS

THIS DOCUMENT, INCLUDING THE INCORPORATED DESIGNS, IS AN INSTRUMENT OF SERVICE FOR THIS PROJECT AND SHALL NOT BE USED FOR ANY OTHER PROJECT WITHOUT THE WRITTEN AUTHORIZATION OF KENNEDY/JENKS CONSULTANTS.

| NO. | REVISION | DATE | BY |
|---|---|---|---|

SCALES
0 1"
0 25mm
IF THIS BAR IS NOT DIMENSION SHOWN, ADJUST SCALES ACCORDINGLY.

DESIGNED SPL
DRAWN SPL
CHECKED PDG

HILLCREST WATER AND SANITATION DISTRICT
GREENWOOD VILLAGE, CO
**SEWER MAINTENANCE MAPS**

Kennedy/Jenks Consultants
DENVER, CO

**2009 CAPITAL IMPROVEMENT RECOMMENDATIONS**

FILE NAME 0946037_MNTS.dwg
JOB NO. 0946037
DATE 4/09
SHEET 1 OF 1